

# CARE INSTRUCTIONS

## PLEASE NOTE

**Regular cleaning and maintenance is important to keep your pulpo product long-lasting.**

Always remove any dirt or marks as soon as possible. We recommend that you first test a small concealed area to ensure that no colour change or damages arise. Do not use materials for maintenance that contain abrasive agents or are acid based – preferably use organic cleaning products.

For the best maintenance of your product, care for it regularly, protect it against direct sunlight and heat and keep it away from moisture, grease and other dirt. Furthermore, surfaces should be protected against contact with sharp or abrasive objects that may leave scratches.

## METAL

For dusting and light cleaning of powder-coated steel use a soft, dry cloth. For further cleaning gently wipe the surface with a soft cloth wrung in clean water and a neutral detergent or soap. Dry immediately afterwards with a soft, dry and clean cloth.

Please note that copper-plated steel develops a patina over time. The darkening or black spotting on the surface is simply oxidation taking place. If left untreated, the surface will eventually develop an even darkness to the entire surface.

## PORCELAIN

For dusting and light cleaning of porcelain use a soft, dry cloth. For further cleaning gently wipe the surface with a soft cloth wrung in clean warm water. Dry immediately afterwards with a soft, dry and clean cloth.

## LIMESTONE

For dusting and light cleaning of limestone use a soft, dry cloth. For further cleaning gently wipe the surface with a soft cloth wrung in clean warm water and a cleaner designed specifically for limestone or in clean warm water and a mild detergent. Dry immediately afterwards with a soft, dry and clean cloth.

## CERAMICS

For dusting and light cleaning of ceramic use a soft, dry cloth. For further cleaning gently wipe the surface with a soft cloth wrung in clean warm water. Dry immediately afterwards with a soft, dry and clean cloth.

## CORDIERITE

For dusting and light cleaning of cordierite use a soft, dry cloth. For further cleaning gently wipe the surface with a soft cloth wrung in clean warm water. Dry immediately afterwards with a soft, dry and clean cloth.

## STONE

For dusting and light cleaning of stone use a soft, dry cloth. For further cleaning gently wipe the surface with a soft cloth wrung in clean warm water. Dry immediately afterwards with a soft, dry and clean cloth.

## BRASS

For dusting and light cleaning of brass use a soft, dry cloth. For further cleaning gently wipe the surface with a soft cloth wrung in clean water and a neutral detergent or soap. Dry immediately afterwards with a soft, dry and clean cloth.

Please note that brass develops a patina over time. The darkening or black spotting on the surface is simply oxidation taking place. If left untreated, the surface will eventually develop an even darkness to the entire surface.

## ALUMINIUM

For dusting and light cleaning of aluminium use a soft, dry cloth. For further cleaning gently wipe the surface with a soft cloth wrung in clean water and a neutral detergent or soap. Dry immediately afterwards with a soft, dry and clean cloth.

## GLASS

For dusting and light cleaning of glass use a soft, dry cloth. For further cleaning gently wipe the surface with a soft cloth wrung in clean water and a non-abrasive commercial glass cleaner. Dry immediately afterwards with a soft, dry and clean cloth.

Please note that bubbles, streaks and other variations in size and colour are part of the production process, and not defects related to the design or production of handmade glass.

## GLASS CERAMICS

For dusting and light cleaning of glass ceramic use a soft, dry cloth. For further cleaning gently wipe the surface with a soft cloth wrung in clean water and a non-abrasive commercial glass cleaner. Dry immediately afterwards with a soft, dry and clean cloth.

## OAK

For dusting and light cleaning of oak use a soft, dry cloth. For further cleaning gently wipe the surface with a soft cloth wrung in clean water and a neutral detergent or soap. Dry immediately afterwards with a soft, dry and clean cloth.

## MDF

For dusting and light cleaning of MDF use a soft, dry cloth. For further cleaning gently wipe the surface with a soft cloth wrung in clean water and a neutral detergent or soap. Dry immediately afterwards with a soft, dry and clean cloth.

## NAPPA LEATHER

For dusting and light cleaning of Nappa leather first try to gently brush off any dirt. If required, vacuum the surface with a soft brush. For further cleaning, mix clean boiled water and a neutral soap to create a foam. Using a wrung soft cloth, gently rub the foam into the leather using a circular motion. Dry immediately afterwards with a soft, dry and clean cloth.

## VELVET, COTTON-VELOUR, LINEN AND WOOL

For dusting and light cleaning of fabrics first try to gently brush off any dirt. If required vacuum the surface with a soft brush. For further cleaning, mix clean water and stain remover. Using a wrung soft cloth, gently rub the mixture into the fabric using a circular motion. Dry immediately afterwards with a soft, dry and clean cloth.

## CARPET

Vacuum rugs regularly using the appropriate attachment. Indentations caused by furniture can usually be removed by vacuuming or brushing.

Always avoid exposure to direct sunlight. To clean rugs, use only warm water and, if needed, a mild soap solution. Rugs can also be cleaned professionally. In the case of heavy soiling or stains, please consult a professional.